









DOC00077 AA.08		MODEL ¹	SENSEAR PART NUMBER				
CONNECTOR PICTURE	MANUFACTURER		SM1R	SM1R I.S.	SM1RDW I.S. ²	smartPlugR / SP1R	smartPlugR I.S. / SP1R I.S.
	ICOM	IC-F4400D, IC-F3400DS, IC-F3261, IC-F3262, IC-F4261, IC-F4262	SRCK6005 (Rev AA.01)	SRCK60050001 (Rev AA.01)			
	HYT / HYTERA	TC610P, TC780, TC3000, TC3600, SIMILO9180, TC700P	SRCK6006B (Rev AA.01)		SRCK6006B001 (Rev AA.01)		
	MOTOROLA	GP328Plus, EX500, EX600, GL2000, GP338Plus, GP344, GP388, PRO5150elite, EXS560XLS, GP628Plus					
	SIMOCO	SRP9180					
	RELM / BENDIX KING	RPV3000, RPV3600, RPU3000, PRU3600, 3300C, RPV7500					
	MOTOROLA	GP328, GP329, GP338, PTX760, MTX960, MTX850, MTX850LS, PRO5150, PRO7550, ATS2500, PR860, HT1250LS+, MTP700, GP1280, GP140, GP320, GP339, GP340, GP360, GP380, GP640, GP650, GP680, HT1250, HT1250LS, HT1550, HT1550XLS, HT750, MTX8250, MTX8250LS, MTX9250, MTX950, PRO5350, PRO5450, PRO5550, PRO5750, PRO7150, PRO7350, PRO7450, PRO9150, PTX700, PTX780, MTX950, MTX900, PRO7750, MTP850Ex, MTP810Ex	SRCK6007B (Rev AA.01)		SRCK6007B001 (Rev AA.01)		
	MINE SITE TECHNOLOGY	MP70					
	MOTOROLA	XTS1500, XTS2500, MT2000, MTX838, MTX8000, XTS2250, XTS3000Astro, XTS5000, MT1500, MTS1500, GP900, GP9000, HT1000, JT1000, MTS2000, MTX9000, MTX-LS, XTS3500, XTS3000, PR1500	SRCK6008B (Rev AA.02)		SRCK6008B001 (Rev AA.02)		
	EF JOHNSON	51SL, 5000 series, 5100 series, 7700 series, Multi-net Ascend					
	KENWOOD	NX-5300, NX-5200, NX-5400, NX-210, NX-210G, NX-200, NX-300, NX-200G, NX-300G, NX-410, NX-411, NX-410K2, TKD-3188, TK-D200, TK-D300, TK-5210, TK-5310, TK-5210G, TK-5310G, TK-5410, TK-5410D, TK-5410G, TK-5220, TK-5320, TK-2180, TK-3180, TK-2180E, TK-2180EMPT, TK-3180E, TK-3180MPT, TK-2140, TK-3140, TK-280, TK285N, TK-290, TK-480, TK-190, TK-380, TK-385, TK-390, TK-481, TK-2041, TK-2180, TK-3148, TK-390	SRCK6011 (Rev AA.02)	SRCK60110001 (Rev AA.01)		SRCK7011 (Rev AA.01)	SRCK70110001 (Rev AA.01)
	EF JOHNSON	VP5000, VP6000	SRCK6011 (Rev AA.02)	SRCK60110001 (Rev AA.01)			
	MOTOROLA MOTOTRBO	MOTOTRBO: XPR7550, XPR7350, DP4801, DP3400, DP3401, DP3600, DP3601, DP4401, DP4800, DP4400, DP4600, XIR P8660, XIR P8668, XIR P8600, XIR P 8608, XIR P8620, DGP5550, DGP8550, DGP5050, DGP8050, XPR6300, XPR6350, XPR6500, XPR6550, XIR P8200, XIRP 8208, XIR P8260, XIR P8268	SRCK6014 (Rev AA.02)	SRCK60140001 (Rev AA.01)		SRCK7014 (Rev AA.01)	SRCK70140001 (Rev AA.01)
	MOTOROLA TETRA	MTP6550, MTP6750, MTP830S, MTP850S					
	MOTOROLA APX	APX8000, APX7000, APX6000, APX5000, APX4000, APX3000, APX2000, APX1000, SRX2200, APX7000L					
	TAIT	TP9300, TP8100, TP8110, TP8115, TP8120, TP8135, TP8140	SRCK6048 (Rev AA.01)				

DOC00077 AA.08		MODEL ¹	SENSEAR PART NUMBER				
CONNECTOR PICTURE	MANUFACTURER		SM1R	SM1R I.S.	SM1RDW I.S. ²	smartPlugR / SP1R	smartPlugR I.S. / SP1R I.S.
MOTOROLA MOTOTRBO SLIM 	MOTOROLA MOTOTRBO SLIM	DP2400, DP2600, XPR3300, XPR3500, DP3441, XiR P6600, XiR P6620, XiR E8608, XiR E8600, DEP550, DEP570, DGP8050 ELITE, XiR E8600, XiR E8606,	SRCK6066 (Rev AA.02)	SRCK60660001 (Rev AA.01)		SRCK7066 (Rev AA.01)	SRCK70660001 (Rev AA.01)
	MOTOROLA TETRA	MTP3100 , MTP3250 , MTP3550					

- PS: 1. Cables in **BLUE** have been partially system tested
 2. SCRK60XXB001 (battery powered) cables have a reduced temperature rating of T3C